

Updated: August 23, 2013**Chief Compliance Officer**

The Chief Compliance Officer (CCO) has primary responsibility for the overall compliance with FERC standards related to the Smoky Mountain Transmission (SMT).

Director of Operations

The Director of Operations is responsible for overall management and oversight of the Smoky Mountain Transmission asset. Reporting to the Vice President of North American Operations, the Director of Operations is accountable for the health, safety, security and environment program of Smoky Mountain Transmission and operating the facilities within Brookfield standards, managing and budgeting annual asset maintenance activities and expenditures and overseeing the development and continuity of the team.

Manager of Operations

The Manager of Operations is responsible for general management and oversight of the Smoky Mountain Transmission asset with the primary responsibility of coordinating technical support regarding operation and maintenance work. Reporting to the Director of Operations, the Manager of Operations also provides general direction and specific project direction to SMT Operations personnel to ensure safe and reliable operation and maintenance of the facilities.

Supervisor

Reporting to the Manager of Operations, the Supervisor is responsible for directing and supervising the activities of employees engaged in the construction, operation, maintenance and repair of electric facilities and associated equipment to insure safe, efficient and reliable energy production in a manner consistent with operation and regulatory requirements.

Associate Maintenance Workers

The Associate Maintenance Workers report directly to the Supervisor and is responsible for hands-on minor troubleshooting, maintenance, repair and operation of Hydro turbine/generator systems, high voltage transmission and distribution, and related equipment.